

Inspection Photos

August 6th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326208

Inspection Document #: 714001040

La Plata County, CO

Township: SENW 13 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Indian Creek Wheeler 13-2
Location ID: 326208

8/6/24
+37.193892,-107.885496
193° S



Photo 1. View of the location taken from the access point facing center.

Inspection Photos

Location Name: Indian Creek Wheeler 13-2

Location ID: 326208





Photo 2. View of deep rutting occurring on the active pad and along the access road. Additional stabilization/grading is needed to minimize degradation to active pad/access road.

Inspection Photos

Location Name: Indian Creek Wheeler 13-2

Location ID: 326208



Photo 3. View of culvert crossing access road that is full of sediment/debris and is no longer functioning. Maintenance and storm water BMPs management is needed.

Inspection Photos

Location Name: Indian Creek Wheeler 13-2

Location ID: 326208



8/6/24
+37.193709,-107.885509
164° S



Photo 4. View of the western interim reclamation area facing south.

Inspection Photos

Location Name: Indian Creek Wheeler 13-2

Location ID: 326208



Photo 5. Reference area comprised of Juniper, Pine and Antelope bitterbrush.