

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2024

Submitted Date:

08/01/2024

Document Number:

694500696**FIELD INSPECTION FORM**Loc ID 316764 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                   | Comment |
|-----------------|-------|-------------------------|---------|
| Trujillo, Helen |       | htrujillo@rlbayless.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 232726      | WELL | SI     | 12/01/2023  | OW         | 107-06140 | DRY CREEK FEDERAL 1-14 | EI          |

**General Comment:**

On 7/31/2024, ECMC staff; Kris Neidel inspected Dry Creek Federal 1-14, part of Remediation Project #19966. The following was observed: Well was SI at time of inspection, HRL compliance solutions was overseeing the removal of an unknown amount of contaminated soil from the former flare pit. Soil was being removed by a mini excavator and being hauled to Milner Landfill. At approximately 16 feet below ground surface, ground water was encountered. A sample of the water was collected for analysis of Table 915-1. Corrective Actions: Ensure all soils are compliant with Table 915-1. Groundwater shall be delineated for Table 915-1.

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 232726 | Type: | WELL | API Number: | 107-06140 | Status: | SI | Insp. Status: | EI |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      | Date:       |           |         |    |               |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| Environmental                        |  |                  |
|--------------------------------------|--|------------------|
| <b>Spill/Remediation:</b>            |  |                  |
| Comment:                             | At approximately 16 feet below ground surface, ground water was encountered. A sample of the water was collected for analysis of Table 915-1 |                  |
| Corrective Action:                   | Ensure all soils are compliant with Table 915-1. Groundwater shall be delineated for Table 915-1.  | Date: 11/30/2024 |
| Emission Control Burner (ECB): _____ |  |                  |
| Comment:                             | _____  |                  |
| Pilot: _____                         | Wildlife Protection Devices (fired vessels): _____   |                  |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403874723    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648844">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648844</a> |
| 694500697    | photos               | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648840">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648840</a> |