

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/01/2024

Document Number:

711901144

FIELD INSPECTION FORMLoc ID 312189 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dizghinjili, Victoria		vdizghinjili@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219319	WELL	IJ	08/01/2019	ERIW	075-06173	KNUDSEN 4	UN

General Comment:[ROUTINE FIR](#)

Location**Lease Road:**

Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action:	REPAIR AND MAINTAIN LEASE ROAD TO COMPLY WITH RULE 204	Date:	08/31/2024
Overall Good: <input type="checkbox"/>			

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	TRASH/DEBRIS CONCRETE		
Corrective Action:	COMPLY WITH RULE 606	Date:	08/08/2024
Type	WEEDS		
Comment:			
Corrective Action:	COMPLY WITH RULE 606	Date:	08/08/2024
Overall Good: <input type="checkbox"/>			

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type: Other	# 0		corrective date
Comment:	NO CHANGE IN EQUIPMENT INVENTORIED		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 219319 Type: WELL API Number: 075-06173 Status: IJ Insp. Status: UN

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403874573	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648601
711901145	PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648553