

Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 8/5/2024



Inspection Photos



Photo 1. Facing north along the access road. There is an erosion gully along the roadside which needs to be repaired. Previous corrective action was not completed.



Inspection Photos



Photo 2. The culvert at this drainage crossing has filled in with sediment and debris and must be cleaned out. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Drone aerial photo facing northeast toward the abandoned wellsite which was never reclaimed. Guyline anchor cable still remains at red arrow. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40001 | Date: 8/5/2024

Inspection Photos



Photo 4. Facing northeast at the wellsite. There is a metal cable guyline anchor that remains at red arrow. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. There are oil stained soils in this area at the abandoned well. Impacted soils need to be excavated and removed. Red arrows point to the areas where stained soil is evident.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40001 | Date: 8/5/2024

Inspection Photos



Photo 6. There is a cement block and guy line anchor that remains at the northeast side of the location which must be removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40001 | Date: 8/5/2024