

Inspection Photos

API: 043-06182

Operator: INCREMENTAL OIL & GAS
(FLORENCE) LLC

Inspection Date: 8/5/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the former access road. The red gravel was brought in by the Operator. This section of the road is now blocked by the fence and needs to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06182 | Date: 8/5/2024

Inspection Photos



Photo 2. Facing northwest further along the access road. There is an erosion channel down the road which needs to be repaired.



Inspection Photos



Photo 3. Facing north along the access road. There is an erosion gully along the roadside which needs to be repaired. Previous corrective action was not completed.



Inspection Photos



Photo 4. The culvert at this drainage crossing has filled in with sediment and debris and has not been cleaned out. Previous corrective action was not completed.



Inspection Photos



Photo 5. Drone aerial photo facing northeast toward the location.



Inspection Photos



Photo 6. Facing southwest at the location. There are areas that are not vegetation and there are also undesirable weeds that need to be controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06182 | Date: 8/5/2024

Inspection Photos



Photo 7. Facing southwest down toward the location. There are areas that are not vegetation and there are also undesirable weeds that need to be controlled. Red arrow points to Russian thistle.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources