

Inspection Photos

08/06/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 418660

Inspection Doc: 696206094

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos show areas of the current working pad that are not necessary for production, and require reclamation. Photos also show weeds have established throughout the current working pad surface of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 3: Photos 3-4 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Photos show areas of the current working pad that are not necessary for production, and require reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 5: Photo example showing weeds have established throughout the current working pad surface of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 6: Photo shows well on Location. Signage does not comport with Rule 605 Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 7: ECMC COGIS imagery. Photo shows flowline systems registered in the area. Photo also shows no Off-location flowline has been registered at the Stewart #36-13H; no other facilities exist on the Location; flowlines from the well likely travel off-location to the tank facility on the Stewart Compressor Location (#423443), to the North of the Stewart Location (#418660).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 418660



Photo 8: 2022 Google Earth aerial imagery. Photo provides an overview of the Stewart #36-13H Location (#418660). Production facilities (not including the well) have either not been installed on the Location, or have since been removed. Red polygons represent approximate areas of the Location that are not necessary for production, and are subject to 1003.b reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources