

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 1 Location.



Photo 2 Location.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 3 Tank Battery sign.



Photo 4 TB.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 5 TB.



Photo 6 TB.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 7 Gas Meter Run, ECDs & Horizontal Heated Separator.



Photo 8 ECDs.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 9 ECDs, The closest has fire damage.



Photo 10 The ground out of the ECD berm appears dry.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 11 The ground out of the ECD berm appears dry.



Photo 12 Gas Meter Run.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 13 Horizontal Heated Separator.



Photo 14 HHS & Vertical Sep..

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 15 ECDs sight glass on pressure gages are melted.



Photo 16 ECDs sight glass on pressure gages are melted.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 17 Damaged ECD melted wire, gauges.



Photo 18 Damaged ECD.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 19 Damaged ECD melted wire, gauges.



Photo 20 Damaged ECD sight glass.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 21 The ground around the ECD appears dry.



Photo 22 Wellsite.

Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 23 WH sign.



Photo 24 WH.



Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 25 Prime mover.



Photo 26 Stained soil on & at the Pump Jack base.



Inspection Photos
Location Name: Christensen 4-9
Location ID: 335580



Photo 27 Stained soil on & at the Pump Jack base.



Photo 28 Pump Jack seal leaking oil onto the PJ base & ground.