

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2024

Submitted Date:

08/08/2024

Document Number:

715800080

FIELD INSPECTION FORM

Loc ID 335580 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288509	WELL	PR	03/01/2024	OW	001-09582	CHRISTENSEN 4-9	SI

General Comment:

[This is a Wellsite & facility Audit/Inspection, Due to a notification of a fire.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Faded, peeling & need to be updated. Install sign to comply with Rule 605.h.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	adequate		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type			
Comment:	Vegetation dead & living throughout location need to be addressed in the near future.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: There was a report of a fire on location at the ECDs, there is no appearance of liquid of any type on the ground around the ECDs.

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated Round stock.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:	Notification of a fire at the ECDs 1 of the ECDs appears to have more damage than the other 2. KPK will conduct a thorough investigation regarding the cause and potential impacts to the environment (if any). A Form 22 regarding the incident will be submitted to the ECMC		
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	automation & telemetry		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Card indicates current calibration		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containment with crude tank			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		39.981890,-104.898920	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	268 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Dead vegetation in & on the berm need to be addressed				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-09582		

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type
Comment:
Corrective Action:
Date:

Inspected Facilities

Facility ID: 288509 Type: WELL API Number: 001-09582 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, Form 22 Initial Accident Report Doc # 403881824.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 8-8-2024 at approximately 1215 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Due to a report of a fire on location. Operator: KP Kauffman Location # 335580 API #05-001-09582 Well name: Christensen 4-9 County: Adams Weather:Overcast, light rain at times Temp: 63* Location: wet While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: Housekeeping: 606 vegetation around location needs to be addressed. Signs Markers/Placards: 605.h placrds on crude tank are faded & peeling. Mechanical Conditions: 608.e Gasket on Pump jack needs to be repaired. Housekeeping: 1002..(2).D Conduct maintenance on equipment, cleanup stained material. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800082	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658369