

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2024

Submitted Date:

08/08/2024

Document Number:

707603085**FIELD INSPECTION FORM**Loc ID 310028 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295590	WELL	TA	05/28/2020	OW	123-25770	NEW CACHE 8-23	PA

**General Comment:**This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Plugging Operations: Cementing; Balanced plug.

Battery: Abandoned.

Abandoned Battery SE corner GPS coordinates: 40.501343 / -104.463021

Well GPS coordinates: 40.502330 / -104.467210

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Jobsite entrance & safety signage posted.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
				corrective date
Type: Plunger Lift	# 0			
Comment:	Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**Facility ID: 295590 Type: WELL API Number: 123-25770 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: JMR Services, LLC

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2392'-2260'Cement Volume (sx): 20 sxsGood Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

2024/08/05:

Plugging Operations: Cementing; Cement-surface.

2024/08/05: JSA attached as photo to this report.

Workover Contractor: JMR Services, LLC Rig #12.

Cement Contractor: JMR Services, LLC.

SAFETY/JSA MEETING. SWC/SYLA, LOCK/OUT TAG OUT. START EQUIPMENT.  
CHECK

GROUNDING (WSEA2-A)

CHECK PSI. CSG 29 PSI. SURFACE 4 PSI. OPEN WELL TO TANK. FLOW CHECK 15  
MIN, WELL

IS STATIC (WSEA 10-A)

TIH W/76 JTS OF 2 3/8 4. 7# J-55 EUE TBG TO 2392

TEST PUMP LINES, PUMP BALANCE PLUG AS FOLLOWS. PUMP 10 BBLS CHEM  
WASH. 20SACS OR 2 BBLS OF 15.8# G-NEAT CMT @1.15 YIELD. DISPLACE 8.8 BBLS FRESH  
WATER.

EST CMT 2392-2260

TOOH W/8 JTS OF 2 3/8 4. 7# J-55 EUE TBG TO 2144. REVERSE OUT W/20 BBLS

UNTIL CLEAN

RETURNS, TOOH SB 12 JTS AND LD 56 JTS

RUWL. PU 4.5 11 .6# RBL LOGGING TOOL AND LOG FROM 2000 FT TO SURFACE.

LOG IN

ATTACHMENTS

WAIT FOR GUNS DUE TO PROCEDURE CHANGE.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/20/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**Comment:

<p>2024/08/05: Plugging Operations: Cementing; Balanced plug. 2024/08/05: JSA attached as photo to this report.</p> <p>Workover Contractor: JMR Services, LLC Rig #12. Cement Contractor: JMR Services, LLC.</p> <p>Reference: Form 6N on file. Notice of Intent to Abandon date: 07/03/2024. Approved. Form 42 on file. Notice of MIRU. Start Date: 07/31/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 08/08/2024. Approved.</p>		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 08/05/2024 at approximately 14:43 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: NEW CACHE-66N63W/8SWNW Location ID: 310028 Well Name(s): New Cache 8-23. API: 123-25770. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Plugging Operations: Cementing; Balanced plug. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.500770 / -104.462860 Well GPS coordinates: 40.502520 / -104.462510</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603086	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658673">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658673</a>