

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

08/02/2024

Document Number:

693807552**FIELD INSPECTION FORM**Loc ID 334173 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, Jake		jroberts@americanhelium.us	<a href="#">All Inspections</a>
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	<a href="#">All Inspections</a>
Demarco, Jaime		jdemarco@blm.gov	
Hartman, Laura		lhartman@blm.gov	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282794	WELL	PR	01/01/2023	GW	113-06205	HC FED 31-31-45-14	SI
282801	WELL	PR	11/01/2019	GW	113-06206	HC FED 31-22-45-14	SI

**General Comment:**

ECMC staff performed a routine field inspection on 7/30/2024.  
 Issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:					
Corrective Action	L				Date:
Type	Main				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 09/02/2024
Type	WELLHEAD				
Comment:	Signs at well not legible. Signs on Meter shed				
Corrective Action:	Corrective Action: Install sign to comply with Rule 605.g.				Date: 09/02/2024
Emergency Contact Number:					
Comment:	435-587-2237 Wrong Emergency contact number				
Corrective Action:	Install sign to comply with Rule 605.d				Date: 09/02/2024
Overall Good: <input checked="" type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Panel fence				
Corrective Action:					Date:
<b>Equipment:</b>					
				corrective date	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 2				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 2				
Comment:					
Corrective Action:					Date:

Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.	
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).	Date: 08/12/2024
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	PLASTIC AST		,
Comment:	Fresh water tank inside housing				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		38.112047,-108.460643
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282794	Type:	WELL	API Number:	113-06205	Status:	PR	Insp. Status:	SI
Producing Well									
Comment:	Plunger lift - Not producing at time of inspection								
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:	11/08/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	24	Fluid Type:	VAPOR					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	282801	Type:	WELL	API Number:	113-06206	Status:	PR	Insp. Status:	SI
Producing Well									
Comment:	Plunger lift - Not producing at time of inspection								
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:	11/08/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	20	Fluid Type:	VAPOR					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**

Survey Type: Routine

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: Long:

Wind: Light Speed: 5 (mph) Direction From: W Weather: Partly Temperature: (F)

Assisting Staff: Camera #: 2

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Separation Equipment
				Wellhead(s)
				Water Tank(s)

Comment: No FLIR detectable gas observed

Corrective Action: Date:

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403875601	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649983">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649983</a>
693807553	Inspection photos 7/30/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649977">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649977</a>