

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

08/02/2024

Document Number:

693807566

FIELD INSPECTION FORMLoc ID 334244 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10453

Name of Operator: PARADOX UPSTREAM LLC

Address: 500 DALLAS ST SUITE #1650

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Demarco, Jaime		jdemarco@blm.gov	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Hartman, Laura		lhartman@blm.gov	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections
Roberts, Jake		jroberts@americanhelium.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
348	WELL	PR	10/20/2011	GW	113-06247	HC FED 25-22-45-15	PR
291573	WELL	PR	09/01/2011	GW	113-06242	HC FED 25-23-45-15	PR

General Comment:

ECMC staff performed a routine field inspection on 7/30/2024.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location**Lease Road:**

Type	Main		
comment:			
Corrective ActionL		Date:	
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/02/2024
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Corrective Action: Install sign to comply with Rule 605.h.	Date:	09/02/2024

Emergency Contact Number:

Comment:	435-587-2237 Wrong Emergency contact number		
Corrective Action:	Install sign to comply with Rule 605.d	Date:	09/02/2024

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe barricade		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.			
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		Date:	08/13/2024
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		38.126276,-108.469292
Comment:	Tank rusted out. Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 09/02/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	348	Type:	WELL	API Number:	113-06247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift - well not producing at time of inspection								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		11/09/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	291573	Type:	WELL	API Number:	113-06242	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift - well not producing at time of inspection								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		11/09/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		20		Fluid Type: VAPOR			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: 5 (mph) Direction From: W Weather: Partly Temperature: 95 (F)Assisting Staff: _____ Camera #: 2☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment
Water Tank(s)
Wellhead(s)
Separation Equipment

Comment: No FLIR detectable gas observedCorrective
Action:

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403875947	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650439
693807567	Inspection photos 7/30/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650432