

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2024

Submitted Date:

08/09/2024

Document Number:

713400216

FIELD INSPECTION FORM

Loc ID 335802 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257138	WELL	PR	04/01/2024	GW	045-07522	CASCADE CREEK 605-23	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 7/25/2024 at approximately 14:18, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC CC/0605-23 Pad at Location ID #335802 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Housekeeping:

- Loose barbed wire around separator/wildlife hazard with a CA date of 8/16/2024
- Multiple debris on location with a CA date of 8/16/2024

Equipment:

- Separator open entry to wildlife/hazard with a CA date of 8/16/2024
- Tank open ended load lines with a CA date of 8/19/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location			
Lease Road:			
	Type	Access	
	comment:	Access	
	Corrective Action		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type	OTHER	
	Comment:	Sign at separator/dehydrator.	
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Sign at entrance to location.	
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:		
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	CONTAINERS	
	Comment:	Chemical tank.	
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	911/1-800-891-6191	
	Corrective Action:		Date: _____
Good Housekeeping:			
	Type	DEBRIS	
	Comment:	Multiple debris on location, refer to photos.	
	Corrective Action:	Comply with CECMC Debris rules.	Date: 08/16/2024
	Type	OTHER	
	Comment:	Loose barbed wire around separator/wildlife hazard, refer to photos.	
	Corrective Action:	Comply with CECMC wildlife rules.	Date: 08/16/2024
Overall Good: <input type="checkbox"/>			

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels/Barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Open entry to wildlife/hazard, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.	Date:	08/16/2024
Type: Other	# 1		
Comment:	Contact tower.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Tank open ended load lines, refer to photos.		
Corrective Action:	All load lines will be capped or plugged.	Date:	08/19/2024
Type: Ancillary equipment	# 1		
Comment:	Chemical tank.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	2	400 BBLs	STEEL AST		
Comment: Telemetry on tanks.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Centralized containment.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 257138 Type: WELL API Number: 045-07522 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Compaction				
Check Dams						
Compaction						
Culverts						
		Ditches				
Berms						
		Check Dams				
		Gravel				
		Berms				
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400217	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659053