

## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Entrance to location - Photo #03910



Wellheads - Photo #03911



## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Separators - Photo #03916



Tank battery/No tank battery sign - Photo #03929



## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Southwest corner of location - Photo #03940



Northwest corner of location - Photo #03941



## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Loose Barbed wire/wildlife hazard - Photo #03923



Loose Barbed wire/wildlife hazard - Photo #03926



## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Holes in containment liner - Photo #03933



Holes in containment liner - Photo #03934

## Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SWSE

Location ID: 335774

Date: 8/1/2024



Holes in containment liner - Photo #03935

