

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2024

Submitted Date:

08/09/2024

Document Number:

701104057

FIELD INSPECTION FORM

Loc ID: 335652 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Morris, Matthew		matthew.morris@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265534	WELL	PR	03/01/2019	GW	045-09022	CHEVRON 33-7D	EG

General Comment:

Flowline Integrity Inspection
Illegible weathered signs at both tank batteries.
Form 42 doc # 403825031
As a result of P&A, equipment will be removed. Flowlines from wellhead to separator will be AIP for safety purposes due to live lines. Will be removed upon final reclaim.
Open excavation from well to separators has been back filled.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Illegible weathered signs at both tank batteries.		
Corrective Action:	Replace battery signage.	Date:	11/15/2024

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 265534 Type: WELL API Number: 045-09022 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104058	Flowline integrity inspection 701104057 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659647