


Operator: 8 NORTH

Location Name: HALEY-RAY-611N61W 21SWSW

Loc ID: 305413

Inspection: 691200008



8 North, LLC

720.370.5540

100BBL

DANGER
PRODUCED WATER
POSSIBLE PETROLEUM CRUDE OIL
POSSIBLE NATURAL GAS CONDENSATE
POSSIBLE CORROSIVE HAZARD
ACUTE AND CHRONIC HEALTH HAZARD

DANGER
OPEN PIT
CONFINED SPACE
DO NOT ENTER







CA: No capacity shown on produced water vault. Install sign to comply with Rule 210.d.

CA Resolution: Operator has installed capacity label to comply with Rule 210.d.











CA: Stained soil at wellhead. Comply with Rule 603.f.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with rule 603.f.

CA: Unused fittings around produced water tank. Comply with Rule 603.f.

CA Resolution: Unused equipment has been removed to comply with 600 series.

CA: Burrows in berms. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

CA Resolution: Operator has completed actions to repair berm.

CA: Stormwater erosion on S. side of location. Install or repair required BMPs per Rule 1002.f.

CA Resolution: Operator has completed actions pertaining to Stormwater Management to comply with ECMC Rule 1002.f.