

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



**Photo 1 – Pumping Unit**



**Photo 2 – Wellhead**

Inspection Photos  
Location Name: Macroni 1-1H  
Location ID: 423680



Energy and Carbon Management Commission  
40.60913, -104.26141, 4877.3ft  
07/23/2024 13:03:55



Energy and Carbon Management Commission  
40.60874, -104.26144, 4889.1ft  
07/23/2024 13:04:27

Photo 3 – Well Sign

Photo 4 – Heater Treater

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Tank Battery**

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



**Photo 7 – Gas Meter, ECD and Flare**



**Photo 8 – Sales Line Valve closed**

Inspection Photos  
Location Name: Macroni 1-1H  
Location ID: 423680




Photo 9 – Sales Line Valves closed





Photo 10 – Sales Meter appears to be Powered Off

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



Energy and Carbon Management Commission  
 40.60856, -104.2614, 4886.3ft  
 07/23/2024 13:06:06




Energy and Carbon Management Commission  
 40.6086, -104.26147, 4887.6ft  
 07/23/2024 13:06:47

**Photo 11 – Calibration Card**

**Photo 12 – Flare Gas Meter**

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



**Photo 13 – Valve Open on Flare Line**



**Photo 14 – Flare Gas Meter**

**Inspection Photos**  
**Location Name: Macroni 1-1H**  
**Location ID: 423680**



**Photo 15 – Flare Valve Open on Flare Line**



**Photo 16 – Valve Open on Flare Line**

Inspection Photos  
Location Name: Macroni 1-1H  
Location ID: 423680



**Photo 17 – ECD – 1" Supply line to Flare in Closed position**



**Photo 18 – Supply line to Flare in Closed position**