

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 3 – ECD and Flare



Photo 4 – Heater Treater and Gas Meter

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 5 – Sales Line Valves in open position






Photo 6 – Sales Line Valves in open position

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Energy and Carbon Management Commission
40.66801, -104.27421, 4997.7ft
07/23/2024 14:55:37

Photo 7 – Sales Meter Calibration Card



Energy and Carbon Management Commission
40.66801, -104.27421, 4999.3ft
07/23/2024 14:56:09


Photo 8 – Static Pressure

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Energy and Carbon Management Commission
40.668, -104.27421, 5002.5ft
07/23/2024 14:56:28

Photo 9 – Yesterday Volume



Energy and Carbon Management Commission
40.66808, -104.27427, 4984.5ft
07/23/2024 14:57:27

Photo 10 – Flare Gas Meter – Appears to be powered off

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457




Photo 11 – Flare Gas Meter



Photo 12 – Valves in Open position to Flare Line

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 13 – Flare and ECD



Photo 14 – Flare – Pilot supply valve open

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 15 – Valves open to Flare



Photo 16 – Wellhead

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 17 – Well Sign




Photo 18 – Pumping Unit