

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 3 – Heater Treater



Photo 4 – Sales Line appears to be in the closed position Upstream of the Sales Meter

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Energy and Carbon Management Commission
40.55413, -104.01897, 4899.9ft
07/24/2024 13:26:10

Photo 5 – Sales Line



Energy and Carbon Management Commission
40.55401, -104.01905, 4875.8ft
07/24/2024 13:27:08

Photo 6 – Sales Meter appears to be powered off

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 7 – Gas Sales Meter Calibration Card



Photo 8 – ECD and Flare Gas Meter

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 9 – Flare inlet Valves appear to be in open position



Photo 10 – Flare Gas Meter

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 11 – Flare Gas Meter – Flow Rate



Photo 12 – Flare Gas Meter – Today Total

Inspection Photos
Location Name: Logan 2H
Location ID: 430811




Photo 13 – Pilot Line appears to be in open position



Photo 14 – Flare Gas Meter – Yesterday Total

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Energy and Carbon Management Commission
40.5543, -104.01883, 4892.8ft
07/24/2024 13:38:26

Photo 15 – Wellhead



Energy and Carbon Management Commission
40.55433, -104.01863, 4886.7ft
07/24/2024 13:38:38

Photo 16 – Gas Engine

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 17 – Pumping Unit