

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Photo 1 – Wellhead



Photo 2 – Well Sign

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Flare and ECD

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Photo 5 – Pilot Supply Valve appears to be in open position



Photo 6 – Inlet Valve to Flare appears to be in open position

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 7 – Gas Sales Line and Meter – Locked Out




Photo 8 – Sales Line – Locked Out

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Photo 9 – Gas Sales Meter appears to be powered off



Photo 10 – Gas Sales Meter – Locked Out

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Photo 11 – Tank Battery Signs



Photo 12 – Flare Line Valves appear to be in open position

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Energy and Carbon Management Commission
40.60331, -104.06671, 4876.2ft
07/24/2024 14:27:18

Photo 13 – Rate – Flare Gas Meter



Energy and Carbon Management Commission
40.60331, -104.06672, 4872.1ft
07/24/2024 14:27:21

Photo 14 – Today Total – Flare Gas Meter

Inspection Photos
Location Name: Buchner 2-2
Location ID: 431634



Energy and Carbon Management Commission
40.60331, -104.06672, 4872.0ft
07/24/2024 14:27:25

Photo 15 – Yesterday Total – Flare Gas Meter



Energy and Carbon Management Commission
40.60331, -104.06703, 4892.4ft
07/24/2024 14:27:54

Photo 16 – Tank Battery

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 17 – Tank Battery Sign