

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 1 – Pumping Unit

Photo 2 – Well Sign

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 3 – Wellhead



Photo 4 – Flare and ECD

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 5 – Pilot Supply Valve appears to be in open position



Photo 6 – Flare and Sales Gas Meters

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041




Photo 7 – Flare Meter – Flow Rate



Photo 8 – Flare Meter

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Energy and Carbon Management Commission
40.6108, -104.05291, 4854.8ft
07/24/2024 14:56:23

Photo 9 – Gas Sales Meter



Energy and Carbon Management Commission
40.61081, -104.0529, 4850.3ft
07/24/2024 14:56:28

Photo 10 – Gas Sales Meter Line open

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Energy and Carbon Management Commission
 40.61078, -104.05292, 4856.4ft
 07/24/2024 14:57:02



Energy and Carbon Management Commission
 40.61084, -104.0528, 4888.4ft
 07/24/2024 14:58:27

Photo 13 – Calibration Card

Photo 14 – Sales Gas Line

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Energy and Carbon Management Commission
40.61096, -104.05277, 4845.1ft
07/24/2024 14:59:06



Energy and Carbon Management Commission
40.61096, -104.05277, 4843.4ft
07/24/2024 14:59:09

Photo 15 – Tank Battery Sign

Photo 16 – Tank Battery

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 17 – Sign at Entrance