

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 1 – Wellhead

Photo 2 – Well Sign

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 3 – ECD



Photo 4 – Flare

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 5 – Pilot Supply Valve appears to be in closed position. Inlet Valve appears to be in the open position



Photo 6 – Heater Treater

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Energy and Carbon Management Commission
40.59801, -104.04291, 4858.2ft
07/24/2024 14:39:35



Energy and Carbon Management Commission
40.59803, -104.04299, 4868.0ft
07/24/2024 14:39:42

Photo 7 – Tank Battery

Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 9 – Gas Sales and Flare Meter

Photo 10 – Gas Sales Meter – Yesterday Volume

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Energy and Carbon Management Commission
40.59797, -104.04285, 4873.2ft
07/24/2024 14:40:49

Photo 11 – Sales Line Valve and Flare Line Valves appear to be in the open position



Energy and Carbon Management Commission
40.59797, -104.04288, 4875.1ft
07/24/2024 14:42:46

Photo 12 – Sales Gas Meter Yesterday Volume

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 13 – Flare Meter – Rate



Photo 14 – Flare Meter – Today Total

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Energy and Carbon Management Commission
40.59795, -104.04289, 4864.2ft
07/24/2024 14:42:12

Photo 15 – Flare Meter – Yesterday Total



Energy and Carbon Management Commission
40.59794, -104.04289, 4866.7ft
07/24/2024 14:43:04

Photo 16 – Sales Line Valve appears to be in the open position