

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2024

Submitted Date:

08/09/2024

Document Number:

696306643

**FIELD INSPECTION FORM**Loc ID 427144 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shepard, DeAnn		dshepard@pedevco.com	All Inspections
Jason Gomez		jason.gomez@state.co.us	
Mattox, Jennifer		jennifer.mattox@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Boyd, William		wboyd@pedevco.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427152	WELL	PR	03/01/2024	OW	123-34880	Reines 1-1H	PR

**General Comment:**

This is a Field Audit for the Well and Tank Battery

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	Candlestick Flare - Pilot supply valves appear to be in the closed position. Inlet valves appear to be in the closed position.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	500 Gallon Propane Tank		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		40.598040,-104.042970
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	YES			
Comment:	East Tank PRV Venting on OGI Video			
Corrective Action:				Date:
<b>Flaring:</b>				
Type	Field Flare			
Comment:	Flaring requires prior approval with a Variance. This well does not have a Gas Capture Plan or Variance. All produced gas is expected to be metered and reported. Form 7 reporting should be corrected to reflect all produced gas volumes (last reported July 2023). Additionally, assure that all CDPHE permissions are in place for flaring.			
Corrective Action:	Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved. Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required.			Date: 08/19/2024

Inspected Facilities									
Facility ID:	427152	Type:	WELL	API Number:	123-34880	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>On Wednesday 07/24/2024 at approximately 14:37, I, Inspector Erica Petrie, conducted a Field Audit at Red Hawk Petroleum LLC, Reines 1-1H, Location #427144 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Audit the following possible Compliance Issues were observed:</p> <p>Flare Gas Meter - No current Calibration Card is visible. Candlestick Flare - Pilot supply valves appear to be in the closed position. Inlet valves appear to be in open position. See photos and OGI Video</p> <p>East Tank PRV venting on OGI Video</p> <p>Sales Line valve appear to be in the open position</p> <p>Flaring requires prior approval with a Variance. This well does not have a Gas Capture Plan or Variance. All produced gas is expected to be metered and reported. Form 7 reporting should be corrected to reflect all produced gas volumes (last reported July 2023). Additionally, assure that all CDPHE permissions are in place for flaring. Correction Action: Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved. Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required. Corrective Action Date 08.19.2024</p> <p>A follow up on this Site Audit will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules. This is a summary of the Audit Report.</p>	petrie	08/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306644	OGI Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660050">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660050</a>
696306645	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660051">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660051</a>