

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2024

Submitted Date:

08/09/2024

Document Number:

705000779

**FIELD INSPECTION FORM**

Loc ID 319426 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243451	WELL	SI	07/01/2020	GW	123-11242	MARTIN T. HART GAS UNIT E TRUE 1	PA
470836	TANK BATTERY	AC	01/10/2020		-	Martin T Hart G U E True 1 battery	EG

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 243451 Type: WELL API Number: 123-11242 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 470836 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Well is plugged and abandoned (Martin Hart GU 1); ECMC form 42 notice of start of plugging operations doc #403756871 received on 04/16/2024. The wellhead flowline has been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. No flowlines/ risers observed. Excavation and remediation work is in progress.	maclarej	08/09/2024
As outlined on COGCC form 19 spill report Doc #403872676 received on 08/02/2024: While conducting flowline removal activities associated with the Hart Martin E True 1 wellhead, historically impacted soil was discovered at the pothole location PH04 (sample FL02). The volume of the release is unknown. Assessment activities are ongoing. The flowline is being permanently removed.	maclarej	08/09/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000780	Signage at PA well	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660361">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660361</a>
705000781	Excavation on location; flowlines removed	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660362">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660362</a>