

## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Aug 1, 2024 at 12:35:29 PM

Photo # 4425 From entrance to location



Aug 1, 2024 at 12:41:58 PM

Photo # 4426 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Photo # 4427 Location



Photo # 4428 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Photo # 4429 Location




Photo # 4430 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Aug 1, 2024 at 12:43:21 PM  
CO

Photo # 4431 Location



Aug 1, 2024 at 12:47:16 PM  
CO

Photo # 4432 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



**Photo # 4433 Dead weeds/debris near thermogen**



**Photo # 4434 Battery sign weathered & cracking/becoming illegible/does not comply with CECMC rules**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Photo # 4435 Staining near wellhead



Photo # 4436 Staining near wellhead



## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Photo # 4437 Staining near wellhead



Photo # 4438 Staining near wellhead



## Inspection Photos

Location Name: TEP Rocky Mountain LLC Mead RWF 43-23 Pad

Location # 419862



Photo # 4439 Improperly marked deadman



Photo # 4440 Same improperly marked deadman from a different angle