

**Operator:** 8 North

**Location Name:** DF RANCH-611N61W 15SESE

**Loc ID:** 410138

**Inspection:** 696300877



Exhibit A



Exhibit B





**Exhibit C**

**CA:** Stained Soil at Exhaust and Gas Engine Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

**CA Resolution:** Operator has provided photo evidence that the stained soil in the exhaust and gas engine area has been addressed in accordance with rule 907.e.