

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2024

Submitted Date:

08/06/2024

Document Number:

713601272**FIELD INSPECTION FORM**Loc ID 429883 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austineexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429883	LOCATION	AC			-	Pathfinder C 14-01 1	RI

General Comment:

This is a follow up of the previous inspections #713600187, #713600366.
The previous inspection corrective actions have not been completed.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	There were noxious weeds previously observed at the west side of the location in the sediment trap. There are undesirable weeds and vegetation growing by the equipment which is a fire hazard.		
Corrective Action:	Comply with Rule 606.	Date:	08/15/2024
Type	UNUSED EQUIPMENT		
Comment:	This well is not producing and is temporarily abandoned. The pumpjack and tanks are unused equipment. All unused equipment must be removed.		
Corrective Action:	Comply with Rule 606.	Date:	09/06/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div>Comment: <div>There are displaced and degraded wattles that need to be repaired. There are rock check dams along the access road that need maintenance. The sediment trap at west side of the location has filled in with sediment. Previous corrective action was not completed.</div></div>						
<div>Corrective Action: <div>Install or repair required BMPs per Rule 1002.f.(2)C</div></div>						Date:
<div>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</div>						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403879315	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6654508
713601273	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6654507