

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2-27 RMV

Location ID: 311537



Photo # 4349 From entrance to location



Photo # 4350 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2-27 RMV

Location ID: 311537



Photo # 4351 Location

Photo # 4352 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2-27 RMV

Location ID: 311537



Photo # 4353 Location



Photo # 4354 Production tank damaged

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2-27 RMV

Location ID: 311537



Photo # 4355 Production tank damaged



Photo # 4356 Production tank damaged