

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2024

Submitted Date:

08/12/2024

Document Number:

707801071

FIELD INSPECTION FORM

 Loc ID 474134 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 ECMC Operator Number: 10409
 Name of Operator: PEAKVIEW OPERATING COMPANY LLC
 Address: 2427 WEST KETTLE CIRCLE
 City: LITTLETON State: CO Zip: 80120
Contact Information:

Contact Name	Phone	Email	Comment
Walters, Steve	720-402-3081	swalters@peakviewenergy.com	
wise, Wayne	(405) 826-7013	wwise@peakviewenergy.com	General contact

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474135	OFF-LOCATION FLOWLINE	AC	12/08/2021		-	Wellhead Line 2	AC
475041	OFF-LOCATION FLOWLINE	AC	03/02/2022		-	2	AC
477783	OFF-LOCATION FLOWLINE	AC	09/01/2020		-	Wellhead Line 2	AC

General Comment:

ECMC Inspection Report Summary

On Wednesday 8/8/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Peakview Grassy Creek Coal #2 tank farm, at Location # 474134 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 474135 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 475041 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477783 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801077	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6663964