

# Inspection Photos

August 12th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326093

Inspection Document #: 714001067

La Plata County, CO

Township: NENE 13 32N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Carter Ute 107  
Location ID: 326093



8/12/24  
+37.020800,-107.880247  
312° NW



Photo 1. View of the location taken from the access point facing center.



Inspection Photos  
Location Name: Carter Ute 107  
Location ID: 326093



**Photo 2.** View of gully erosion head forming on the southern edge of the disturbance, with channelized flows running through the southern interim reclamation area and evidence of sediment transport off of the location.



Inspection Photos  
Location Name: Carter Ute 107  
Location ID: 326093



**Photo 3.** Unmarked guyline anchor on the active pad.



Inspection Photos  
Location Name: Carter Ute 107  
Location ID: 326093



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of Juniper, Antelope bitterbrush and Indian ricegrass.

API #: 067-07459