

# Inspection Photos

08/09/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335467

**Inspection Doc:** 696206110

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335467



**Photo 1:** Photos show hay storage in close proximity of production equipment. Hay is currently being stored between two Locations: the GGU VAN ORDSTRAND-66S91W/30NESW Location (#335467) and the GIBSON GULCH UNIT-66S91W/30NESW Location (#335294)



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335467



August 9, 2024



August 9, 2024

**Photo 2:** Photos 2-4 taken from the interim areas of the Location. Photos show that interim reclamation is not progressing towards ECMC 1003 Reclamation requirements; interim areas are predominantly bare, or vegetated by Undesirable Plant Species. Perennial establishment that was observed was sparse.

Noxious weed establishment, including Jointed Goatgrass and Field Bindweed observed throughout interim areas of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335467



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335467



**Photo 4:** See comments under photo 2. Photo left example showing Jointed Goatgrass establishment on the interim areas; photo right example showing Field Bindweed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335467



**Photo 5:** ECMC COGIS imagery. Photo shows flowline systems registered in the area; no Off-location flowlines have been registered at the VAN ORDSTRAND Location; no other facilities exist on the Location; flowlines from the wells likely travel off-location to the tank facility on the GIBSON GULCH UNIT-66S91W/30NESW (#335294), to the west of the Van Ordstrand Location (#335467).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources