

Inspection Photos

08/09/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264

Inspection Doc: 696206112

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



August 9, 2024



August 9, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



August 9, 2024

Photo 3: Photo taken from the west end of the Location. Photo shows 4 large tires, possibly placed by the surface owner for feeding livestock, stored on the Location. Tires are not necessary for use on the Location and require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



Photo 4: Stained soils at loadline.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



Photo 5: Photo taken from the interim areas on the southeast end of the Location. Photos show that interim reclamation is not progressing towards ECMC 1003 Reclamation requirements; interim areas are predominantly bare, or vegetated by Undesirable Plant Species. Grass observed in the photos is Jointed Goatgrass.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335264



Photo 6: Photo taken from the interim areas on the north end of the Location. Photos show that interim reclamation is not progressing towards ECMC 1003 Reclamation requirements; interim areas are predominantly bare, or vegetated by Undesirable Plant Species; weeds observed in photo include Kochia, Field Bindweed and Jointed Goatgrass.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources