

# Inspection Photos

08/09/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335052

**Inspection Doc:** 696206122

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 1:** Signage at battery and tanks have been maintained.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN

Location ID: 335052



**Photo 2:** Photos taken from the east end of the Location. Photo shows areas not progressing towards 1003 standards; unable to find evidence that additional reclamation work has been performed. Photo also show erosion degradation has persisted; stormwater and erosion control BMPs have not been installed or maintained.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 3:** Continued from photo 2. BMPs to minimize erosion and degradation have not been implemented; erosion degradation has persisted. Additional reclamation efforts have also not been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 4:** Continued from photo 2. BMPs to minimize erosion and degradation have not been implemented; erosion degradation has persisted. Additional reclamation efforts have also not been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



August 9, 2024



August 9, 2024

**Photo 5:** Photos taken from the northeast end of the Location. Stormwater erosion, degradation and sediment transport due to runoff has persisted on the Location. BMPs to manage stormwater have not been implemented or maintained.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 7:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 8:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 9:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 10:** Photos show culvert on the southwestern location entrance has not been maintained.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 11:** Continued from photo 10. Photo shows culvert outlet; culvert on the southwestern location entrance has not been maintained.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 12:** Photos taken from the sediment trap on the southwest end of the Location. BMP has not been installed or maintained in proper functioning condition; BMP has not been installed with a properly engineered outlet; geotextile lining in conjunction with the rip-rap material not observed; slopes within outlet lack stabilization and erosion degradation / sediment transport is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



**Photo 13:** See comments under photo 12.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources