

Operator: 8 North

Location Name: WELD-611N61W 28NENW

Loc ID: 310704

Inspection: 684905215



Exhibit A



Exhibit B



Exhibit C

CA: Stained soil at exhaust, in engine house- Comply with rule 603.f.

CA Resolution: Operator has provided photo evidence that the stained soil at exhaust, in engine house has been addressed in compliance with the 600 series.