

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2024

Submitted Date:

08/14/2024

Document Number:

715200693

FIELD INSPECTION FORMLoc ID 324865 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213314	WELL	PR	04/01/2023	OW	061-06676	MUNDHENKE-KNOW HEIRS 1	PR

General Comment:

Routine Field Inspection for OWP

Location				
Lease Road:				
Type	Access			
comment:	Dirt road through farm ground			
Corrective Action				Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Lease sign by tanks			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Lease sign mounted to fence at unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<input type="text"/>			Date: _____
Corrective Action:	<input type="text"/>			
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Tubing on the south side of unit			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Some wire panels around unit and wellhead			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Emission Control Device	# 1			
Comment:	ECD on south side of treater			
Corrective Action:				Date:
Type: Vertical Heater Treater	# 1			
Comment:	Treater on east side of tank battery			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Ajax E-42			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 54B		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.469360,-102.425470	
Comment:	Green fiberglass tank					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		38.469360,-102.425470	
Comment:	West tank is oil tank					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	213314	Type:	WELL	API Number:	061-06676	Status:	PR	Insp. Status:	PR
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Well is SI at time of inspection and in the process of transferring to OWP</div>									
Corrective Action: <div></div> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200702	Wellhead and unit photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666045
715200703	tank battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666046
715200704	pumping unit, stained soil and prime mover	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666047
715200705	treater and ECD	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666048