

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2024

Submitted Date:

08/14/2024

Document Number:

715200695

**FIELD INSPECTION FORM**

Loc ID 324852 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 61250  
Name of Operator: MULL DRILLING COMPANY INC  
Address: 1700 N WATERFRONT PKWY B#1200  
City: WICHITA State: KS Zip: 67206-

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
OBryhim, Reesa		ROBryhim@mulldrilling.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213221	WELL	PR	07/03/1997	OW	061-06583	WICKERSHAM 1	PR

**General Comment:**

[Routine Field Inspection](#)

Location			
<b>Lease Road:</b>			
	Type Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
	Type BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tanks. Labeling is faded and needs repainted and replaced		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type PUMP JACK		
Comment:	Wire panels around unit. Some panels are removed and neatly stored		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 2		corrective date
Comment:	Phase converter, electric panel and propane tank by separator		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	National 228		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	ECD on south side of separator		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:	HHS on west side of tank battery		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		38.469520,-102.436130
Comment:	West tank is for water production				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	200 BBLs	FIBERGLASS AST		38.469520,-102.436130
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 213221 Type: WELL API Number: 061-06583 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Tank battery is 2700' SW @ 38.469520/-102.436130 by CR 59](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200699	wellhead photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666051">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666051</a>
715200700	Tank battery	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666052">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666052</a>