

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2024

Submitted Date:

08/07/2024

Document Number:

708201489**FIELD INSPECTION FORM**Loc ID 419018 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419013	WELL	PA	11/22/2021	GW	123-32101	ROTHE 44-30	RI
419018	LOCATION	CL			-	Roth 44-30	RI

**General Comment:**[This is a Final Reclamation Inspection for PA Well API#123-32101. Well was plugged and abandoned 11/22/2021.](#)

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					corrective date
Type:		#			
Comment:		No visual evidence of oil and gas equipment at the well location. Refer to the attached inspection photos.			
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	419013	Type:	WELL	API Number:	123-32101	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	419018	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental	
<b>Spill/Remediation:</b>	
Comment:	Remediation Projects (#20408; 02/08/2022 ) and (#20410; 07/19/2022) have been closed and approved under Form 27s.
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment:	<div></div>
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use:    IRRIGATED

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment

Corrective Action                       Date                     

1002b. SOIL REMOVAL AND  
SEGREGATION                     

Comment

Corrective Action                       Date                     

1002c. PROTECTION OF SOILS                     

Comment

Corrective Action                       Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment

Corrective Action                       Date                     

1003a. Waste and Debris removed?                     

Comment

Corrective Action                       Date                     

Unused or unneeded equipment onsite?                     

Comment

Corrective Action                       Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment

Corrective Action                       Date                     

Guy line anchors marked?                     

Comment

Corrective Action                       Date

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed Pass

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage Pass

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: The well location (Location ID 419018 with API 123-32101) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas. Operator is required to submit a Form 44 Off-Location Flowline Abandonment Notice per Rule 1105.f.(2), therefore, this location will remain "In-Process" until ECMC receives the required notice. Refer to attached inspection photos.

Inspector Name: Edwardson, Dylan

Corrective Action: <input type="text"/>					Date <input type="text"/>		
Overall Final Reclamation		In Process		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>	
<b>Storm Water:</b>							
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment	
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
Comment:		<input type="text" value="At the time of this inspection, no stormwater erosion issues were observed. Location has achieved final stabilization with cropland vegetation."/>					
Corrective Action:		<input type="text"/>				Date: <input type="text"/>	
Pits:		<input type="checkbox"/> NO SURFACE INDICATION OF PIT					

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403883235	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658373">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658373</a>
708201500	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658367">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6658367</a>