

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2024

Submitted Date:

08/15/2024

Document Number:

698602157

**FIELD INSPECTION FORM**

Loc ID: 303977    Inspector Name: St John, William (Cal)    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE    State: CO    Zip: 80424

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253866	WELL	PR	01/08/1996	GW	125-07744	ROUNDTREE 1-27	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type			
Comment:	Well sign posted on gas meter shed at well location.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Emergency contact information posted on well sign.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve not connected. Casing valve open.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Gas Meter Shed.		
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:	Drive motor removed.		
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 8-1-24. Meter Calibration/Test Log dated 5-30-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253866 Type: WELL API Number: 125-07744 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Tubing valve not connected. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 6/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602203	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666638">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666638</a>