

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2024

Submitted Date:

08/09/2024

Document Number:

701104061

FIELD INSPECTION FORM

Loc ID 335582 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------------------|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 265297 | WELL | PR | 03/01/2019 | GW | 045-08997 | CHEVRON 22-8D | EG |

General Comment:

[Flowline Integrity Inspection and Tank Integrity Inspection](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | BATTERY | | |
| Comment: | Illegible weathered signs at tank battery. | | |
| Corrective Action: | Replace battery signage. | Date: | 11/15/2024 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Comment: | <input type="text"/> | Date: | <input type="text"/> |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-------------------------------------|----------|------|---------|--------|
| CONDENSATE | 1 | 300 BBLs | | | |
| Comment: | Manhole plate off on back off tank. | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | New berm around tank. | | | |
| Corrective Action: | | | Date: | |

Venting:

| | |
|----------|--|
| Yes/No | |
| Comment: | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 265297 Type: WELL API Number: 045-08997 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 403884945 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660176 |
| 701104062 | Flowline integrity inspection 701104061 photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660159 |