

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2024

Submitted Date:

07/30/2024

Document Number:

696306609

**FIELD INSPECTION FORM**Loc ID 424707 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Boyd, William		wboyd@pedevco.com	<a href="#">All Inspections</a>
Shepard, DeAnn		dshepard@pedevco.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	
Jennifer Mattox		jennifer.mattox@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424715	WELL	PR	11/01/2023	OW	123-34144	Planck 1-14H	PR

**General Comment:**[This is a Field Audit of the Well and Tank Battery](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil at Wellhead; see photos		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	08/23/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	500 Gallon Propane Tank		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Sales Line appears to be in open position		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLS	STEEL AST		40.667780,-104.279400	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:	Flaring requires prior approval with a Variance. This well does not have a Gas Capture Plan or Variance. All produced gas is expected to be metered and reported. Form 7 reporting should be corrected to reflect all produced gas volumes (last reported June 2023). Additionally, assure that all CDPHE permissions are in place for flaring.	
Corrective Action:	Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved. Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required.	Date: <u>08/19/2024</u>

Inspected Facilities									
Facility ID:	424715	Type:	WELL	API Number:	123-34144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>On Tuesday 07/23/2024 at approximately 14:40, I, Inspector Erica Petrie, conducted a Field Audit at Red Hawk Petroleum LLC, Plank 1-14H, Location #424707 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Audit the following possible Compliance Issues were observed:</p> <p>Sales Line appears to be in open position</p> <p>Flaring requires prior approval with a Variance. This well does not have a Gas Capture Plan or Variance. All produced gas is expected to be metered and reported. Form 7 reporting should be corrected to reflect all produced gas volumes (last reported June 2023). Additionally, assure that all CDPHE permissions are in place for flaring. Correction Action: Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved. Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required. Corrective Action Date 08.19.2024</p> <p>A follow up on this Site Audit will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules. This is a summary of the Audit Report.</p>	petrie	07/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403884832	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660075">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660075</a>
696306610	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660018">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660018</a>
696306623	OGI Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660019">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6660019</a>