

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/09/2024

Document Number:

713400226

## FIELD INSPECTION FORM

 Loc ID: 335774  
 Inspector Name: Popejoy, Dusty  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202
**Findings:**

- 16 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		cogcc.inspections@caerusoil ndgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269990	WELL	PR	03/01/2019	GW	045-09435	CHEVRON/TEXACO 24C-12D	PR
270032	WELL	PR	03/01/2019	GW	045-09439	CHEVRON/TEXACO 34C-12D	PR
270033	WELL	PR	03/01/2019	GW	045-09440	CHEVRON/TEXACO 31C-13D	PR

**General Comment:**[CECMC Inspection Report Summary](#)

On 8/1/2024 at approximately 13:19, Compliance Inspector Dusty Popejoy conducted an on-site inspection at CAERUS PICEANCE LLC CHEVRON/TEXACO-66S97W/12SWSE at Location ID #335774 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

## Housekeeping:

1- Loose barbed wire/wildlife hazard with a CA date of 8/16/2024

## Tanks and Berms:

2- Holes in secondary containment liner with a CA date of 8/29/2024

## Signs/Marker:

3- No tank battery sign with a CA date of 9/9/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access.		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No tank battery sign, refer to photos.		
Corrective Action:	Comply with CECMC Singage rules.		Date: 09/09/2024
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Loose barbed wire/wildlife hazard, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.		Date: 08/16/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbed wire fence.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire fence.		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	All Bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Thermo gen.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Telemetry on tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment:	Holes in secondary containment liner, refer to photos.			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			Date: 08/29/2024

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 269990 Type: WELL API Number: 045-09435 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270032 Type: WELL API Number: 045-09439 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270033 Type: WELL API Number: 045-09440 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				
		Compaction				
Berms						
		Culverts				
Ditches						
		Ditches				
Sediment Traps						
		Berms				
Gravel						
		Sediment Traps				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403884402	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659650">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659650</a>
713400227	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659648">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6659648</a>