

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2024

Submitted Date:

08/16/2024

Document Number:

715200725

**FIELD INSPECTION FORM**Loc ID 304583 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 266896      | WELL | PR     | 11/10/2005  | GW         | 125-08729 | HILLTOP 13-4  | PR          |

**General Comment:**

Routine Field Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action  |                           | Date: |  |

Overall Good: ☒

|                      |                     |       |  |
|----------------------|---------------------|-------|--|
| <b>Signs/Marker:</b> |                     |       |  |
| Type                 | WELLHEAD            |       |  |
| Comment:             | Lease sign by fence |       |  |
| Corrective Action:   |                     | Date: |  |

|                           |       |  |  |
|---------------------------|-------|--|--|
| Emergency Contact Number: |       |  |  |
| Comment:                  |       |  |  |
| Corrective Action:        |       |  |  |
|                           | Date: |  |  |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | PUMP JACK   |       |  |
| Comment:           | Metal panels around unit, wellhead, VGS and meter run |       |  |
| Corrective Action: |   | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Ancillary equipment | # 2  |       |                 |
| Comment:                  | Electric panel and telemetry equipment         |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Pump Jack           | # 1  |       |                 |
| Comment:                  | Jensen unit                                    |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Prime Mover         | # 1  |       |                 |
| Comment:                  | Electric motor                                 |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Gas Meter Run       | # 1  |       |                 |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Vertical Separator  | # 1  |       |                 |
| Comment:                  | Vertical gas separator 50% buried by meter run |       |                 |
| Corrective Action:        |  | Date: |                 |



| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 266896                       | Type: | WELL | API Number: | 125-08729 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                |   |
|--------------|----------------|---|
| Document Num | Description    | URL   |
| 715200738    | location photo | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668117">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668117</a> |