

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2024

Submitted Date:

08/15/2024

Document Number:

715200727

FIELD INSPECTION FORM

Loc ID 337885 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289269	WELL	PR	06/21/2007	GW	125-10718	STULTS 22-4	PR

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
	Type	Access	
	comment:	Two track through pasture	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign by fence	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	PUMP JACK	
	Comment:	Metal panels around unit, wellhead, VGS and meter run	
Corrective Action:			Date:

Equipment:			corrective date
Type:	Ancillary equipment	# 2	
	Comment:	Electric panel and telemetry equipment	
Corrective Action:			Date:
Type:	Pump Jack	# 1	
	Comment:	Weatherford unit	
Corrective Action:			Date:
Type:	Prime Mover	# 1	
	Comment:	Electric motor	
Corrective Action:			Date:
Type:	Gas Meter Run	# 1	
	Comment:		
Corrective Action:			Date:
Type:	Vertical Separator	# 1	
	Comment:	Vertical gas separator 50% buried by meter run	
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 289269 Type: WELL API Number: 125-10718 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200728	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668120