

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2024

Submitted Date:

08/16/2024

Document Number:

717900022

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 4680

Name of Operator: DCP OPERATING COMPANY LP

Address: 2331 CITYWEST BLVD., S812-02

City: HOUSTON State: TX Zip: 77042

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Nikki Graber		nikki.graber@state.co.us	
Jeremy Ferrin		jeremy.ferrin@state.co.us	
Ansel, Ivan	970-378-6367	iansel@dcpmidstream.com	Operations Supervisor
Kari Brown		kari.brown@state.co.us	
Park, Paul	(970) 378-6372	PDPark@dcpmidstream.com	All Plant Inspections

**General Comment:**

This is an environmental inspection for Spill ID 486404 CR57/CR6 Flowline/Gathering Line. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

This inspection was in response to a spill that occurred on March 25, 2024. P66 was notified by a third-party operator of a suspected release to the surface of what appeared to be condensate mixed with water from a gas gathering line operated by P66 at the spill location.

As access was restricted by vegetation and a gate/fence, ECMC was not able to get close enough for detailed photos of the spill site, but from the vantage point of the inspector, it appeared no activity has occurred at the spill location.

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Due to a failure to close this spill out with CAs or via a Form 27 within 90 days, the Operator is currently in violation Rule 912.b.(6) (90 day spill closure).

Corrective Action: Operator shall submit an a Form 19 closure request. Date: 08/23/2024

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Approximately 69 barrels (bbls) of mixed liquids was removed from the surface and transported to the Pawnee Waste facility for disposal. Due to Eagle nesting and fledging periods, work activities have been postponed until after July 1, 2024.	robinsotl	08/16/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900023	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668742">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668742</a>