

Interim Reclamation and Stormwater Inspection

Date: 08/13/2024

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC - 10633

Location ID: 331608

Inspection Document #: 708201512

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 1. Undesirable vegetation (kochia and russian thistle) observed on the northwest portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 2. Erosion degradation (riling) observed on the northwest portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 2. Continued from Photo 2. Evidence of sediment transport into the interim areas west of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 4. Undesirable vegetation (e.g. kochia and russian thistle) observed along the northwest portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 5. Erosion degradation (riling) observed on the northwest portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 6. Erosion degradation (riling) observed on the northwest portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 7. Erosion degradation (riling) and sediment transport into adjacent lands observed on the north portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 8. Continued from Photo 7; evidence of asphalt/road armour material on adjacent lands.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 9. Erosion degradation and undesirable vegetation along the location's access road.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 10. Undesirable vegetation (russian thistle) observed along the eastern portion of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 11. Russian olive (CO List B Noxious Weed) in red arrow; undesirable vegetation and trash observed near the southeast portion of the location.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 12. Erosion degradation observed south of the tank battery.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 13. Continued from Photo 12; photo illustrates sediment transport onto lower portions of the access road/production areas.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 14. Unused equipment and debris observed within production equipment.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 15. Erosion degradation (riling) along the southern portion of the location, near production equipment.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



8/13/24, 11:25 AM
35° NE
ECMC

Photo 16. Trash and debris observed on the southern portion of the location.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 17. No apparent stormwater control measures observed on the southwest corner of the location, near adjacent irrigation ditch.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 18. Erosion degradation observed on the northwest corner of fenced production equipment; no apparent stormwater control measures near adjacent irrigation ditch (green arrow).

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photos 19 & 20. Erosion degradation and evidence of off location sediment transport observed on the northwest portion of the fenced production equipment.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 21. Unused equipment/debris observed on the northern portion of the interim areas (red arrow-fence). Additionally, the interim areas (background) do not appear to be progressing towards reclamation standards with no desirable perennial vegetation observed.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 22. Continued from Photo 21.

Inspection Photos
Location Name: Chapin 61N65W/4 SESE
Location ID: 331608



Photo 23. Erosion degradation observed at the outlet of control measure.