

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2024

Submitted Date:

08/16/2024

Document Number:

708302594

FIELD INSPECTION FORM

Loc ID 335978 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299283	WELL	PR	05/19/2010	GW	045-17639	N. PARACHUTE EF09C-21 D27A 5	PR
299284	WELL	PR	05/28/2010	GW	045-17640	N. Parachute EF01D-28 D27A 5	PR
299285	WELL	PR	04/21/2010	GW	045-17641	N. PARACHUTE EF12D-22 D27A 5	PR
299286	WELL	PR	03/23/2010	GW	045-17642	N. PARACHUTE EF13B-22 D27A 5	PR
299287	WELL	PR	05/22/2010	GW	045-17643	N. PARACHUTE EF09A-21 D27A 5	PR
299288	WELL	PR	10/27/2008	GW	045-17644	N. PARACHUTE EF11C-22 D27A 5	PR
299289	WELL	PR	03/07/2010	GW	045-17645	N. PARACHUTE EF11A-22 D27A 5	PR
299290	WELL	PR	03/28/2010	GW	045-17646	N. PARACHUTE EF06A-22 D27A 5	PR
299291	WELL	PR	04/19/2010	GW	045-17647	N. PARACHUTE EF05C-22 D27A 5	PR
299292	WELL	PR	04/29/2010	GW	045-17648	N. PARACHUTE EF05A-22 D27A 5	PR
299293	WELL	PR	03/08/2010	GW	045-17649	N. PARACHUTE EF14A-22 D27A 5	PR
299294	WELL	PR	03/21/2010	GW	045-17650	N. PARACHUTE EF06C-22 D27A 5	PR
299295	WELL	PR	05/10/2010	GW	045-17651	N. PARACHUTE EF09D-21 D27A 5	PR
299299	WELL	PR	03/31/2010	GW	045-17652	N. PARACHUTE EF13C-22 D27A 5	PR

299386	WELL	PR	04/18/2010	GW	045-17662	N. PARACHUTE EF12A-22 D27A 5	PR
413296	WELL	PR	03/31/2010	GW	045-18771	N. PARACHUTE EF04A-27 D27A 5	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 8/14/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW at Location ID #335978 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Open-ended line on gas meter
- 2) Wildlife entry hazard on produced water tank

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Gas meter/lift protected by concrete barriers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment: Chemical tanks		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 16	
Comment: Open-ended line on gas meter.		Date:
Corrective Action: Secure line to comply with Rule 608.e.		Date: <u>08/21/2024</u>
Type: Gas Meter Run	# 16	
Comment: Gas lift		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment: Wildlife protective screen on produced water tank does not provide sufficient protection. Screen has been damaged by thief hatch.		Date:
Corrective Action: Repair/reinstall wildlife protective screen.		Date: <u>08/21/2024</u>

Venting:

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type		
Comment:		Date:
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299283	Type:	WELL	API Number:	045-17639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299284	Type:	WELL	API Number:	045-17640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299285	Type:	WELL	API Number:	045-17641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299286	Type:	WELL	API Number:	045-17642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299287	Type:	WELL	API Number:	045-17643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299288	Type:	WELL	API Number:	045-17644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299289	Type:	WELL	API Number:	045-17645	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299290	Type:	WELL	API Number:	045-17646	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299291 Type: WELL API Number: 045-17647 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299292 Type: WELL API Number: 045-17648 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299293 Type: WELL API Number: 045-17649 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299294 Type: WELL API Number: 045-17650 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299295 Type: WELL API Number: 045-17651 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299299 Type: WELL API Number: 045-17652 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299386 Type: WELL API Number: 045-17662 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	413296	Type:	WELL	API Number:	045-18771	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Material Handling And Spill Prevention		
		Gravel				
Compaction						
		Compaction				
		Ditches				
Berms						
Gravel						

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302595	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668962