

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Energy & Carbon Management Commission
40.11418, -104.94266, 4910.5ft, 129°
08/19/2024 12:34:37

Photo 1 Location tall vegetation inside and outside of the fencing.



Energy & Carbon Management Commission
40.11408, -104.94251, 4888.2ft, 13°
08/19/2024 12:35:12

Photo 2 WH sign.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 3 WH.



Photo 4 Electric panel and pump jack.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 5 Tall vegetation throughout location.



Photo 6 WH sign.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 7 WH.



Photo 8 Electric panel and pump jack.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 9 Transformers, meter boxes.



Photo 10 Tall vegetation throughout location.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 11 WH sign.



Photo 12 WH.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 13 Electric panel and pump jack.



Photo 14 Tall vegetation throughout location.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 15 WH sign.



Photo 16 WH.

Inspection Photos
Location Name: Frederick Unit A1
Location ID: 336452



Photo 17 Electric panel and pump jack.



Photo 18 Location tall vegetation inside and outside of the fencing.