

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2024

Submitted Date:

08/19/2024

Document Number:

715800099

**FIELD INSPECTION FORM**

Loc ID 318225 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240919	WELL	SI	06/01/2021	GW	123-08707	GUADAGNOLI 2	SI

**General Comment:**

[Follow up wellsite inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	vegetation along access rd needs to be addressed.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate, the sign is fading and will need to be replaced in the near future.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Live/dead tall vegetation & trash (debris) along access road & throughout location inside fencing and outside of fencing. Comply with Rule 606, 3-29-224.		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panels & meter box.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240919 Type: WELL API Number: 123-08707 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** SI since 5-2021 & last produced 4/2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. 4/21/2024

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/25/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

**Comment:** plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
ECMC Inspection Report Summary On Monday 8-19-2024 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This is a 901 order follow up field inspection to FIR Doc # 702403221. Operator: KP Kauffman Location name: Location ID # 318225 Well Name: Guadagnoli 2 API # 05-123-08707 County: Weld Weather: Mostly cloudy & warm. Location: Dry. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues have not been addressed and are delinquent: 606 housekeeping: Vegetation 7 Debris, CA date 3-29-2024. 417.b MIT: Shut in wells, CA date 4-21-2024. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules. Any Corrective Actions from previous inspections not addressed are still applicable.	revasr	08/19/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800100	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6671000">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6671000</a>