

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2024

Submitted Date:

08/19/2024

Document Number:

708302601

**FIELD INSPECTION FORM**

Loc ID: 335970      Inspector Name: Morris, Matthew      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER      State: CO      Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8      Number of Comments  
0      Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301038	WELL	PR	07/22/2010	GW	045-18075	N. PARACHUTE EF11A-28C28A595	PR
301039	WELL	PR	07/28/2010	GW	045-18076	N. PARACHUTE EF03A-33C28A 5	PR
301040	WELL	PR	11/13/2010	GW	045-18077	N. PARACHUTE EF05A-28C28A 5	PR
301041	WELL	PR	08/18/2010	GW	045-18078	N. PARACHUTE EF05C-28C28A 5	PR
301042	WELL	PR	07/26/2010	GW	045-18079	N. PARACHUTE EF11D-28C28A 5	PR
301043	WELL	PR	07/01/2010	GW	045-18080	N. PARACHUTE EF06D-28C28A 5	PR
301044	WELL	PR	08/01/2022	GW	045-18081	N. PARACHUTE EF06A-28C28A 5	PR
301045	WELL	PR	06/27/2010	GW	045-18082	N. PARACHUTE EF14D-28C28A595	PR
301046	WELL	PR	07/27/2010	GW	045-18083	N. PARACHUTE EF14B-28C28A595	PR
301047	WELL	PR	07/12/2010	GW	045-18084	N. PARACHUTE EF12B-28C28A595	PR
301048	WELL	PR	08/18/2010	GW	045-18085	N. PARACHUTE EF12C-28C28A595	PR
301049	WELL	PR	06/27/2010	GW	045-18086	N. PARACHUTE EF03D-28C28A 5	PR

**General Comment:**

CECMC Inspection Report Summary

On 8/14/2024 at approximately 13:15, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/28NENW at Location ID #335970 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Small weeds present across location.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters/lift protected by concrete barriers.		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 12		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 12		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	301038	Type:	WELL	API Number:	045-18075	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301039	Type:	WELL	API Number:	045-18076	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301040	Type:	WELL	API Number:	045-18077	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301041	Type:	WELL	API Number:	045-18078	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301042	Type:	WELL	API Number:	045-18079	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301043	Type:	WELL	API Number:	045-18080	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301044	Type:	WELL	API Number:	045-18081	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301045	Type:	WELL	API Number:	045-18082	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301046 Type: WELL API Number: 045-18083 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301047 Type: WELL API Number: 045-18084 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301048 Type: WELL API Number: 045-18085 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301049 Type: WELL API Number: 045-18086 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Compaction				
Gravel						
		Ditches				
Compaction						
		Gravel				
		Culverts				
Berms						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302602	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6671191">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6671191</a>