

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2024

Submitted Date:

08/20/2024

Document Number:

714201493

FIELD INSPECTION FORMLoc ID 430972 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430973	WELL	PR	07/01/2021	GW	123-36362	POWERS 4C-27HZ	PR
430974	WELL	PR	09/01/2018	GW	123-36363	POWERS 4N-27HZ	PR
430975	WELL	PR	07/01/2021	OW	123-36364	POWERS 30N-27HZ	PR
430976	WELL	PR	10/01/2017	OW	123-36365	POWERS 30C-27HZ	PR

General Comment:

This is an audit of POWERS 30N-27HZ scout card and related documents followed by a field inspection.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	panel			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Plunger Lift	# 4			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 4			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	430973	Type:	WELL	API Number:	123-36362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; valves appear to be in the open position.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		05/08/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type: None			
		End Surf Csg Pressure:		--					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	430974	Type:	WELL	API Number:	123-36363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; valves appear to be in the open position.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		05/08/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type: None			
		End Surf Csg Pressure:		--					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	430975	Type:	WELL	API Number:	123-36364	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; valves appear to be in the open position.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		05/08/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type: None			
		End Surf Csg Pressure:		--					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	430976	Type:	WELL	API Number:	123-36365	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; valves appear to be in the open position.							
Corrective Action:								Date:	

BradenHead	
Date of Last Brhd Test: 05/08/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 1 Fluid Type: None
	End Surf Csg Pressure: --
Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Routine inspection. Weather conditions: sunny, dry ground.	santistb	08/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201494	Wellhead photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6671931