

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/12/2024

Submitted Date:

08/20/2024

Document Number:

707801082**FIELD INSPECTION FORM**Loc ID 424711 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS INCAddress: 13635 E 104TH AVENUE STE 400City: COMMERCE CITY State: CO Zip: 80022**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wccassistant@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424708	WELL	SI	10/01/2023	OW	107-06242	Dawson Creek 1-25	SI

General Comment:**ECMC Inspection Report Summary**

On Monday 8/19/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Beaman Dawson Creek 1-25, at Location # 424711 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Secondary containment has holes
2. Weeds throughout location and growing inside of tank containment
3. Random debris
4. Access road is unstable and needs maintained

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-970-276-3887/1-970-629-9895/1-970-210-2896/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds throughout location and growing inside of tank containment		
Corrective Action:	Remove weeds	Date:	09/20/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/30/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane tank		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Work over rig and associated equipment on location and a form 42 was recived stating of move in day 8/19/24	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				Inadequate
Comment:	Secondary containment has holes			
Corrective Action:	Install or maintain liner material to ensure spill or released materials will be maintained with containment structure.			Date: 09/20/2024

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	424708	Type:	WELL	API Number:	107-06242	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Last produced 10/23"/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Ditches				
		Rip Rap				
		Gravel				Sparse to none
Berms						

Comment: 1. Access road is unstable and needs maintained. Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.

Corrective Action: The agency requires that the operators develop an erosion and sedimentation control (E&SC) plan that meets local the standards and specifications. Install, maintain or provide documentation of post construction management plan or BMP's.

Date: 09/27/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801083	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672151